



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
BANNERDALE ROAD	O/S 171	Dying		Crataegus monogyna	Plant in verge in same position o/s 173	Crataegus laevigata 'Paul's Sc
BANNERDALE ROAD	O/S 102	Dead	Dead	Prunus serrulata	Plant in verge directly o/s 102 (same as felled tree)	Crataegus lavalleei 'Carriere
BANNERDALE ROAD	O/S 192-194	Damaging and Dangerous	Damage to Surface	Prunus Amanogawa	Plant in verge o/s - between 192-194 (same as felled tree)	Prunus X hillieri 'Spire'
BANNERDALE ROAD	O/S 176-178	Dying		Prunus serrulata	Plant in verge o/s - between 176-178 (same as felled tree)	Prunus X hillieri 'Spire'
BANNERDALE ROAD	O/S 294	Damaging	Damage to Surface	Prunus sp	Plant in verge o/s 294 (same as felled tree)	Malus 'Rudolph'
BANNERDALE ROAD	O/S 83	Damaging	Damage to Surface	Prunus serrulata	Plant in verge centrally between 83-85	Prunus X hillieri 'Spire'

BANNERDALE ROAD	O/S 167-169	Dangerous	Structural Integrity	Prunus serrulata	Plant in verge centrally between 167-169 (same as felled tree)	Prunus X hillieri 'Spire'
BANNERDALE ROAD	O/S 195-197	Damaging	Damage to Surface	Prunus serrulata	Plant in verge centrally between 195-197 (same as felled tree)	Malus 'Rudolph'
BANNERDALE ROAD	O/S 203-205	Damaging	Damage to Surface	Prunus serrulata	Plant in verge centrally between 203-205 (same as felled tree)	Malus 'Rudolph'
BANNERDALE ROAD	O/S 223-225	Damaging	Damage to Surface	Prunus sp	Plant in verge centrally o/s- between 223-225 (same as felled tree)	Malus 'Rudolph'